



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program June 24, 2013

Reviewed: PPB

Mine Name: Black Sands 47281	Permit Number: S/47/0084
Operator Name: Black Sands Holding Co.	Inspection Date: 06/18/2013
Inspector(s): Tom Nicolaysen (intern)	Time: 4:30 PM
Other Participants:	Mine Status: Inactive

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Permit Fees: Paid 01/20/2013

Bond Amount: \$18,600

Purpose of Inspection:

Inspection of reclamation for bond release

Inspection Summary:

Unable to locate drill hole. Some re-vegetation.

Conclusions and Recommendations:

The site should be released from bond

Inspector's Signature Tom Nicolaysen

cc: Operator

O:\M047-Uintah\S0470084-BlackSands47281\inspections\ins06182013-84





Access to the site is west of the gate to T.M.E. Asphalt Ridge. The short road to the pad is just over the berm to the left.



There is some re-vegetation on the pad, just in front of a small stream bed.
UTM NAD 83: E 628442.93, N 4465721.75



Looking from the drill site up to the road. Some remnant of the access road remains but it is not a significant impact.